## **EAST Search History**

Ref	Hits	Search Query	DBs	Default	Plurals	Time Stamp
#		,		Operator		
S27	1347	(361/103,91.2).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/01/24 12:13
S28	569	S27 and (irreversible damage open)	US-PGPUB; USPAT	OR	ON	2007/01/08 16:09
S29	729	S27 and (irreversible damage open)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/01/08 16:09
S30		S29 and (resist\$3 adj (sensor detector))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/01/08 16:11
S31	4	S27 and (resist\$3 adj (sensor detector))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/01/08 16:11
S32	105	(arc and (irreversible impaired open) and (resistance (electrical adj property) conductivity)).CLM.	US-PGPUB	OR	ON	2007/01/24 11:18
S33	10	(arc and (irreversible impaired open fus\$3) and (resistance (electrical adj property) conductivity) and (cable wire) and power).CLM.	US-PGPUB	OR	ON	2007/01/24 11:21
S34	22	(arc and (irreversible impaired open fus\$3) and detect\$3 and (cable wire) and power).CLM.	US-PGPUB	OR	ON	2007/01/24 11:21
S35	176	(361/103,91.2).CCLS.	US-PGPUB	OR	OFF	2007/01/25 09:33
S36	1	("20040252429").PN.	US-PGPUB	OR .	OFF	2007/01/24 12:16
S37	118	(361/62).CCLS.	US-PGPUB	OR	OFF	2007/01/24 12:18
S38 .	698	(361/104).CCLS.	USPAT	OR	OFF	2007/01/25 09:34
S39	61	S38 and (overtemperature heat\$3) and arc	US-PGPUB; USPAT	OR	ON	2007/01/25 09:36

## **EAST Search History**

S40	60	S39 and (conductor line power)	US-PGPUB; USPAT	OR	ON	2007/01/25 09:37
S41	61	S39 and (disconnect melt fuse open)	US-PGPUB; USPAT	OR	ON	2007/01/25 09:38
S42	. 46	S41 and (protect safety)	US-PGPUB; USPAT	OR	ON	2007/01/25 09:40
S43	32	S42 and (fiber wire)	US-PGPUB; USPAT	OR	ON .	2007/01/25 09:41
S44	8	S42 and (fiber)	US-PGPUB; USPAT	OR	ON	2007/01/25 09:41